

MEL	ITEM	(Dx)	Cat	Inst	Req
28-12-01c	Overpressure Protectors Center Tank (A330-200 with Mod. 58623/MP H16147 and Mod. 200281/MP H16151, A330-300 with Mod. 204025/MP H166901)		B	1	0
May be damaged or missing provided:					

Operational Procedures:

1. Crossfeed valve is checked operative on the ECAM FUEL page.
2. Both center tank fuel pumps are operative.
3. Center and inner tanks fuel quantity indications are operative on the ECAM FUEL page.
4. **(Dx)** Maximum fuel on board (FOB) is **154,322 lbs (70,000 kg)**.

Additional Operational Procedures:

None required.

Maintenance Procedures:

1. Fuel distribution is performed in accordance with the maintenance procedure.

Placarding

1. Place M-74B on Center Console.

FEDERAL AVIATION ADMINISTRATION

AIRCRAFT:

REV NO. 22-1

PAGE NO.

AIRBUS A330

DATE 16 NOV 2022

2-2

MEL	ITEM			Cat	Inst	Req
34-48-01	Ground Proximity Warning System (GPWS)			A	1	0
May be damaged or missing provided:						

Operational Procedures:

1. Alternate procedures are established and used.
2. Repairs are made within 2 flight-days.

Additional Operational Procedures:

None required.

Maintenance Procedures:

None required.

Placarding

1. Place M-74B on Center Console.